

**Model 5190-D
Temperature/Humidity Probe
User's Manual**



CONTENTS

- THEORY OF OPERATION 1**
 - Power Supply 1
 - Output Signals 1
 - Environmental Limits..... 1
 - Temperature Limits..... 1
 - Humidity Limits 1
 - Temperature Compensation 1
 - Sensor Protection 2

- INSTALLATION & CHECKOUT 2**
 - Probe Location..... 2
 - Wiring Connections..... 2
 - MARS Installation 2

- MAINTENANCE 3**
 - Cleaning or Replacing the Dust Filter 3
 - Periodic Calibration Check..... 3
 - Periodic Maintenance (AWOS Installations) 3
 - Equipment Required..... 3
 - Monthly Maintenance 3
 - Quarterly Maintenance 3
 - Annual Maintenance 4

- SPECIFICATIONS 4**

- WARRANTY 5**

- AWOS WARRANTY 5**

THEORY OF OPERATION

The Model 5190-D Temperature/Humidity Probe is designed for a variety of environmental monitoring applications, including All Weather Inc.'s Automated Weather Observing Systems (AWOS). The 5190-D operates with a DC supply voltage and has a low current draw. Relative humidity is measured with a thin-film capacitor sensor, and temperature is measured using a Pt100 RTD with an accuracy of $\pm 0.3^\circ\text{C}$. The signals from the sensors are converted into two linearized voltage output signals.

POWER SUPPLY

The 5190-D requires a voltage source in the range of 3.5-50 VDC, capable of providing 4 mA.

In the case of data logger applications, battery power can be conserved by energizing the probe for only 15 seconds during each measurement.

OUTPUT SIGNALS

The 5190-D provides two linearized voltage signals:

Parameter	Output Voltage	Range
<i>RH</i>	0-1.0 VDC	0-100% RH
<i>Temp.</i>	0-1.0 VDC	-40 to +60°C

⚠ *Do not connect a load to the outputs with an impedance of less than 10k Ω .*

ENVIRONMENTAL LIMITS

Temperature Limits

The 5190-D was designed to operate within the range of -40°C to $+60^\circ\text{C}$.

Humidity Limits

The 5190-D can operate within 0 and 100% RH. Direct condensation does not damage the sensors. However, the humidity sensor will not provide correct readings when condensation is present, and neither of the sensors will operate if the sensor leads are short-circuited by condensation. The 5190-D provides a humidity output that is referenced to the saturated water vapor pressure above liquid water. With this reference, the maximum humidity reading at temperatures below freezing are as follows:

100% RH at 0°C	95% RH at -5°C	91% RH at -10°C
87% RH at -15°C	81% RH at -20°C	78% RH at -25°C
75% RH at -30°C		

TEMPERATURE COMPENSATION

Practically every make of relative humidity sensor requires a compensation for the effect of temperature on the humidity output signal in order to measure accurately over a wide range of temperature conditions. In the specific case of an instrument using a capacitive sensor, compensation is required because the dielectric characteristics of both the water molecule and the hygroscopic polymer used in the sensor vary with temperature. The electronic circuit of the 5190-D uses data from the Pt100 temperature sensor to

automatically compensate the effect of temperature on the accuracy of humidity measurement.

SENSOR PROTECTION

Always use the dust filter provided with the probe to protect the sensors. The standard wire mesh filter is sufficient for most applications. For applications that involve direct spraying of water and/or a lot of dust, use the optional foam filter.

INSTALLATION & CHECKOUT

PROBE LOCATION

Install the probe so that the local conditions at the sensors are typical of the environment to be measured.

In an outdoor environment:

- Use either a shield or a shelter to protect the probe and sensors from direct exposure to solar radiation and precipitation. Several shields are available from All Weather Inc., including the Model 8190 Motor Aspirated Radiation Shield (MARS).
- In an open field, install the probe at least 3.3 feet (one meter) above ground. Increase this distance if the ground surface is concrete or blacktop (such as above a roof).

WIRING CONNECTIONS

The 5190-D is supplied with a 3-meter cable (about 9.8 ft) terminated with tinned ends. When a much longer cable is required (max. 100 feet or 30 meters), consider using an extension cable.

Connect the wires as follows:

Wire	Color	TB2 Terminal
Ground / -	Gray, Blue, and Shield	4
Supply Voltage (+)	Green	3
RH	White	2
Temperature	Brown	1

Check for wiring errors before powering the probe. Improper wiring may damage the probe.

☞ Whenever possible, we recommend grounding the (-) side of the probe supply voltage.

MARS INSTALLATION

If the Model 8190 Motor Aspirated Radiation Shield (MARS) is used with the 5190-D probe, refer to the 8190 MARS User's Manual (8190-001) for installation instructions.

Note: In AWOS installations where a 5190-D is installed in a MARS, if the MARS fan fails, temperature and dew point will both be reported as missing.

MAINTENANCE

CLEANING OR REPLACING THE DUST FILTER

The dust filter should be cleaned annually, depending on the conditions of measurement. Whenever possible, cleaning should be done without removing the filter from the probe. Clean the filter with a small brush to remove any debris that may have accumulated on the filter.

To replace the filter, unscrew the filter from the probe, replace the filter in the housing, and reinstall the filter assembly.

☞ If you remove or replace the filter, make sure that the sensors do not get caught. The humidity sensor is sometimes mistaken for a “white paper tag”. Do not remove the probe! Before putting on a new dust filter, check the alignment of both sensors with the probe. The wires that connect the sensors to the probe are very thin and bend easily. If this happens, correct the alignment by holding the sensor very gently with a pair of small flat nosed pliers. Do not puncture the sensor with sharp pliers or tweezers or pull too hard on the sensor.

PERIODIC CALIBRATION CHECK

Long term stability of the humidity sensor is typically better than 1% RH per year. For maximum accuracy, calibration of the unit should be verified once a year by returning the probe to All Weather Inc. Applications where the probe is exposed to significant pollution may require more frequent verification. Both the Pt100 RTD temperature sensor and associated electronics are very stable and should not require any calibration after the initial factory adjustment.

PERIODIC MAINTENANCE (AWOS INSTALLATIONS)

Equipment Required

Equipment required for periodic maintenance of the Model 5190-D consists of:

- Psychrometer
- Psychrometric calculator (All Weather Inc. Model 5282-A)

All Weather Inc. sells many types of psychrometers, including the Model 5230 Assmann Psychrometer and the Model 5211 Sling Psychrometer. Contact All Weather Inc. for ordering information.

Monthly Maintenance

Monthly maintenance of the Model 5190-D consists of checking the 8190 MARS and cleaning it if dust or debris is observed.

Quarterly Maintenance

Quarterly maintenance of the Model 5190-D consists of performing the monthly maintenance tasks, cleaning the dust filter if dust or debris is observed, and checking the accuracy of the 5190-D against readings made using a psychrometer as explained below.

- 1 Position the psychrometer in close proximity to the intake of the motor aspirated radiation shield. Allow a minimum of 20 minutes for psychrometer conditioning before proceeding.

- 2 Prepare the psychrometer after the waiting period by wetting the wet bulb wick with distilled water.
- 3 Wind the psychrometer fan motor to provide constant aspiration (Assmann psychrometer only).
- 4 Begin taking measurements 1.5 minutes after the psychrometer starts running. Record the psychrometer temperature, wet bulb temperature, 5190-D temperature, and 5190-D dew point temperature at 1 minute intervals.
- 5 Individually average all readings of psychrometer temperature and 5190-D temperature that are within $\pm 1^{\circ}\text{F}$ ($\pm 0.56^{\circ}\text{C}$). Subtract the average psychrometer temperature from the 5190-D temperature. For AWOS installations, check the pass status on the data sheet if the result is within $\pm 2^{\circ}\text{F}$ ($\pm 1.1^{\circ}\text{C}$). If the sensor fails, replace it and return the failed sensor to All Weather Inc. for calibration.
- 6 Individually average all readings of wet bulb temperature that are within $\pm 0.5^{\circ}\text{F}$ ($\pm 0.28^{\circ}\text{C}$) of each other. Calculate the dew point temperature from the average psychrometer temperature and the average wet bulb temperature using the psychrometric calculator. Subtract the calculated dew point temperature from the AWOS dew point temperature. Check the pass status if the result is within $\pm 3^{\circ}\text{F}$ ($\pm 1.7^{\circ}\text{C}$). Replace the sensor if the sensor fails, and return the failed sensor to All Weather Inc. for recalibration.

Annual Maintenance

Annual maintenance consists of performing the monthly maintenance tasks and checking the accuracy of the 5190-D against readings made using a psychrometer according to the procedure prescribed for quarterly maintenance above.

SPECIFICATIONS

Humidity Sensor	Thin Film Capacitor
Temperature Sensor	Pt100 RTD
Operating Temperature Limits	-40 to +60°C
Humidity Output Signal (linear)	0-1.0 VDC = 0-100% RH
Temperature Output Signal (linear)	0-1.0 VDC = -40 to +60°C
Minimum Load per Output	10k Ω
Accuracy (at 23°C)	$\pm 1.5\%$ RH $\pm 0.3^{\circ}\text{C}$
First Signal After Measurement Interval	2.3 s 0.7 s
Supply Voltage	3.5-50 VDC
Current Consumption	approx. 3 mA
Cable Length	3 meters (10 ft.), tinned ends
Sensor Protection	wire mesh filter
Dimensions	8.19" (208mm) long, 0.59" (15 mm) diameter
Weight	0.27 lb. (120g)

WARRANTY

Unless specified otherwise, All Weather Inc. (the Company) warrants its products to be free from defects in material and workmanship under normal use and service for one year from date of shipment, subject to the following conditions:

- (a) The obligation of the Company under this warranty is limited to repairing or replacing items or parts which have been returned to the Company and which upon examination are disclosed, to the Company's satisfaction, to have been defective in material or workmanship at time of manufacture.
- (b) The claimant shall pay the cost of shipping any part or instrument to the Company. If the Company determines the part to be defective in material or workmanship, the Company shall prepay the cost of shipping the repaired instrument to the claimant. Under no circumstances will the Company reimburse claimant for cost incurred in removing and/or reinstalling replacement parts.
- (c) This warranty shall not apply to any Company products which have been subjected to misuse, negligence or accident.
- (d) This warranty and the Company's obligation thereunder is in lieu of all other warranties, express or implied, including warranties of merchantability and fitness for a particular purpose, consequential damages and all other obligations or liabilities.

No other person or organization is authorized to give any other warranty or to assume any additional obligation on the Company's behalf, unless made in writing and signed by an authorized officer of the Company.

AWOS WARRANTY

This equipment has been manufactured and will perform in accordance with requirements of FAA Advisory Circular 150/5220-16C. Any defect in design, materials, or workmanship which may occur during proper and normal use during a period of 1 year from date of installation or a maximum of 2 years from shipment will be corrected by repair or replacement by All Weather Inc.



allweatherinc

All Weather Inc.

1165 National Drive
Sacramento, CA 95818
Fax: 916.928.1165
Phone: 916.928.1000
Toll Free: 800.824.5873

5190-D-001
Revision C
ECO 0860
September, 2006